
ROBOZE ARGO 500 HYPERSPEED MR

ARGO 500 HS- Technical datasheet - ENG [01]

Revision Date:02.2026



1. DIMENSIONS

External	1985mm x 1436mm x 2375 mm | 76.2in x 56.5in x93.5in
Build volume	500mm x 500mm x 500mm | 19.7in x 19.7in x 19.7in
Shipping Box[1]	2100mm x 1700mm x 2430mm | 87.8inx68.9inx96.9in
Machine Weight	1500 kg | 3307 lb

[1] Moisture control system shipped separately

All information contained herein is derived from standardized tests conducted under normal and controlled operating conditions. Printer performance (both in relation to print speed, accuracy, and/or quality of the finished product) can vary depending on many factors, such as operating conditions, material used, construction parameters, geometry and dimensions of the finished part, part orientation, and post-processing method. Therefore, the information and images herein are merely representative and do not constitute any binding agreement on service levels or warranties, contractual or statutory, of quality, subsistence of certain properties, suitability for a particular purpose, or marketability of the 3D printer. It is the responsibility of the end user of the printer to determine its suitability, safety, and appropriateness for its intended use, as well as to verify that use of the printer is in compliance with all applicable laws. The user of the printer assumes all risks related to or arising from the 3D printed parts, including all risks and liabilities arising from the use, possession, distribution, sale, marketing, operation and/or, performance of the 3D printed parts manufactured with the printer.

ROBOZE ARGO 500 HYPERSPEED MR

ARGO 500 HS- Technical datasheet - ENG [01]

Revision Date:02.2026

2. ACCURACY

XY	10 µm | 393.70 µin
Z	25 µm | 984.25 µin

3. MECHANICS

Structure	High-performance structure made of aluminum bars and steel cover
Linear system	Precision ball linear bars in ground steel
X and Y axis movement	Mechatronic movement with C5 hardened helical rack and pinion
Z axis movement	Precise C6 ball screw system
HT Dryers	No. 4 HT dryers reaching up to 120 °C
Filament loading	Automatic filament loading system
Filament monitoring	Automated filament monitoring by fiber optic sensor and mechanical encoder

4. ELECTRONICS

Control System	PLC (Programmable Logic Controller)
Motors	High-performance motors Brushless for precise movement

All information contained herein is derived from standardized tests conducted under normal and controlled operating conditions. Printer performance (both in relation to print speed, accuracy, and/or quality of the finished product) can vary depending on many factors, such as operating conditions, material used, construction parameters, geometry and dimensions of the finished part, part orientation, and post-processing method. Therefore, the information and images herein are merely representative and do not constitute any binding agreement on service levels or warranties, contractual or statutory, of quality, subsistence of certain properties, suitability for a particular purpose, or marketability of the 3D printer. It is the responsibility of the end user of the printer to determine its suitability, safety, and appropriateness for its intended use, as well as to verify that use of the printer is in compliance with all applicable laws. The user of the printer assumes all risks related to or arising from the 3D printed parts, including all risks and liabilities arising from the use, possession, distribution, sale, marketing, operation and/or, performance of the 3D printed parts manufactured with the printer.

ROBOZE ARGO 500 HYPERSPEED MR

ARGO 500 HS- Technical datasheet - ENG [01]

Revision Date:02.2026

Peak Power Absorbed	9.6 kW [2]
Average Power Absorbed	6.2 kW[3]
Certifications	CE, UL Certified [4]
Electrical Supply	400Y / 230 VAC, 50 / 60 Hz, 3PH+N+PE, 25 A[5]
Electrical Transformer	Required for the US market
Plug/Bare Wire	IEC 60309, 32 A (3P+N+PE / 6H)[6]
Display	Large, user-friendly interface, 13" Display Touch Screen

5. PNEUMATICS

Pressure	Minimum pressure required: 6.2 bar / 90 psi
Air	Maximum consumption at full load: 533 L/min (19 CFM): • 356l/min (12.5CFM) Machine • 177l/min (6.5 CFM)Moisture filter
Vacuum system	Vacuum system for adhesion of polymeric sheets on inox steel buildplate
Moisture control	Industry top class dew point sensor and adsorption filter up to -80°C dew point

[2] Value extrapolated during chamber heating from room temperature (RT) to 175°C.

[3] Value extrapolated during printing with a heated chamber up to 175°C.

[4] Main panel

[5] Solidly Grounded Wye System Only

[6] Bare wire connection for the US

All information contained herein is derived from standardized tests conducted under normal and controlled operating conditions. Printer performance (both in relation to print speed, accuracy, and/or quality of the finished product) can vary depending on many factors, such as operating conditions, material used, construction parameters, geometry and dimensions of the finished part, part orientation, and post-processing method. Therefore, the information and images herein are merely representative and do not constitute any binding agreement on service levels or warranties, contractual or statutory, of quality, subsistence of certain properties, suitability for a particular purpose, or marketability of the 3D printer. It is the responsibility of the end user of the printer to determine its suitability, safety, and appropriateness for its intended use, as well as to verify that use of the printer is in compliance with all applicable laws. The user of the printer assumes all risks related to or arising from the 3D printed parts, including all risks and liabilities arising from the use, possession, distribution, sale, marketing, operation and/or, performance of the 3D printed parts manufactured with the printer.

ROBOZE ARGO 500 HYPERSPEED MR

6. CONNECTION

OPC-UA	Industrial communication protocol support
Connectivity	USB Type B output, WiFi & Ethernet connectivity

7. MATERIALS

CARBON PEEK

PEEK

ULTEM™ AM9085F

CARBON PA PRO

KRONOS B2

KRONOS S1

PP PRO

8. ON DEMAND MATERIALS

PEKK

STRONG-ABS NATURAL

STRONG-ABS RED

FUNCTIONAL-NYLON

All information contained herein is derived from standardized tests conducted under normal and controlled operating conditions. Printer performance (both in relation to print speed, accuracy, and/or quality of the finished product) can vary depending on many factors, such as operating conditions, material used, construction parameters, geometry and dimensions of the finished part, part orientation, and post-processing method. Therefore, the information and images herein are merely representative and do not constitute any binding agreement on service levels or warranties, contractual or statutory, of quality, subsistence of certain properties, suitability for a particular purpose, or marketability of the 3D printer. It is the responsibility of the end user of the printer to determine its suitability, safety, and appropriateness for its intended use, as well as to verify that use of the printer is in compliance with all applicable laws. The user of the printer assumes all risks related to or arising from the 3D printed parts, including all risks and liabilities arising from the use, possession, distribution, sale, marketing, operation and/or, performance of the 3D printed parts manufactured with the printer.

ROBOZE ARGO 500 HYPERSPEED MR

ARGO 500 HS- Technical datasheet - ENG [01]

Revision Date:02.2026

ULTRA-PLA NATURAL

ULTRA-PLA BLACK

9. SLICING SOFTWARE

Proprietary	SlizeR
Commercial	Simplify3D

10. PRINTING PROCESS

Patented tool change system	Patented hardware and software system that reduces tool change time to <10s
Dual pinch extruder	New extruder feeding system with dual pinch for high-speed printing
High-temp dual extruder	Dual extruder with extrusion temperature up to 500 °C
Bed leveling	Automatic bed mesh leveling for thermal-expansion compensation
Heated chamber	Heated chamber up to 180 °C
Material presets	Preset material configurations
Continuous feeding	Automatic continuous material feeding system

All information contained herein is derived from standardized tests conducted under normal and controlled operating conditions. Printer performance (both in relation to print speed, accuracy, and/or quality of the finished product) can vary depending on many factors, such as operating conditions, material used, construction parameters, geometry and dimensions of the finished part, part orientation, and post-processing method. Therefore, the information and images herein are merely representative and do not constitute any binding agreement on service levels or warranties, contractual or statutory, of quality, subsistence of certain properties, suitability for a particular purpose, or marketability of the 3D printer. It is the responsibility of the end user of the printer to determine its suitability, safety, and appropriateness for its intended use, as well as to verify that use of the printer is in compliance with all applicable laws. The user of the printer assumes all risks related to or arising from the 3D printed parts, including all risks and liabilities arising from the use, possession, distribution, sale, marketing, operation and/or, performance of the 3D printed parts manufactured with the printer.

ROBOZE ARGO 500 HYPERSPEED MR

ARGO 500 HS- Technical datasheet - ENG [01]

Revision Date:02.2026

Live monitoring and print report	Live monitoring and recording of components, consumables, and process data automatically logged into a part specific print report
Clog detection	Automatic clog detection with encoder

All information contained herein is derived from standardized tests conducted under normal and controlled operating conditions. Printer performance (both in relation to print speed, accuracy, and/or quality of the finished product) can vary depending on many factors, such as operating conditions, material used, construction parameters, geometry and dimensions of the finished part, part orientation, and post-processing method. Therefore, the information and images herein are merely representative and do not constitute any binding agreement on service levels or warranties, contractual or statutory, of quality, subsistence of certain properties, suitability for a particular purpose, or marketability of the 3D printer. It is the responsibility of the end user of the printer to determine its suitability, safety, and appropriateness for its intended use, as well as to verify that use of the printer is in compliance with all applicable laws. The user of the printer assumes all risks related to or arising from the 3D printed parts, including all risks and liabilities arising from the use, possession, distribution, sale, marketing, operation and/or, performance of the 3D printed parts manufactured with the printer.